

Health o meter®

Professional

Pelstar, LLC • 11800 South Austin Avenue • Alsip, IL 60803 • USA • Phone: 800-815-6615 • Fax: 800-654-7330

Combine the weight shown on the small and large poise then add 88lbs.				Combine the weight of the small and large poise then add 150lbs.			
Counter weight between 50 & 100 Large poise weight at 250		Counter weight between 50 & 100 Move large poise to 300		Counter weight between 150 and 200 Large poise weight at 250		Counterweight between 150 and 200 Move large poise to 300	
If the scale reads	The patient's weigh is	If the scale reads	The patient's weigh is	If the scale reads	The patient's weigh is	If the scale reads	The patient's weigh is
262	350	301	389	275	425	301	451
263	351	302	390	276	426	302	452
264	352	303	391	277	427	303	453
265	353	304	392	278	428	304	454
266	354	305	393	279	429	305	455
267	355	306	394	280	430	306	456
268	356	307	395	281	431	307	457
269	357	308	396	282	432	308	458
270	358	309	397	283	433	309	459
271	359	310	398	284	434	310	460
272	360	311	399	285	435	311	461
273	361	312	400	286	436	312	462
274	362	313	401	287	437	313	463
275	363	314	402	288	438	314	464
276	364	315	403	289	439	315	465
277	365	316	404	290	440	316	466
278	366	317	405	291	441	317	467
279	367	318	406	292	442	318	468
280	368	319	407	293	443	319	469
281	369	320	408	294	444	320	470
282	370	321	409	295	445	321	471
283	371	322	410	296	446	322	472
284	372	323	411	297	447	323	473
285	373	324	412	298	448	324	474
286	374	325	413	299	449	325	475
287	375	326	414	300	450	326	476
288	376	327	415			327	477
289	377	328	416			328	478
290	378	329	417			329	479
291	379	330	418			330	480
292	380	331	419			331	481
293	381	332	420			332	482
294	382	333	421			333	483
295	383	334	422			334	484
296	384	335	423			335	485
297	385	336	424			336	486
298	386					337	487
299	387					338	488
300	388					339	489
						340	490
						341	491
						342	492
						343	493
						344	494
						345	495
						346	496
						347	497
						348	498
						349	499
						350	500